DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 99.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-024550 Address: 333 Burma Road **Date Inspected:** 16-May-2011

City: Oakland, CA 94607

OSM Arrival Time: 1500 **Project Name:** SAS Superstructure **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC) Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yan Hua No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Vikram Singh was present during the times noted above for observations relative to the work being performed at ZPMC.

NDT

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 09150.

Magnetic Particle Testing (MT)

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date. The member is identified as 14W. The weld designations reviewed is as follows:

SEG3020Z-080, 081 SEG3020AA-024

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 09151.

Magnetic Particle Testing (MT)

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date. The member is identified as 13AE. The weld designations reviewed is as follows:

SEG3007AD-023, 025, 027, 040, 042, 044, 046~049, 054~057, 062~065, 070~073, 102, 103, 106, 107 SEG3007AA-043~046, 050~053, 057~060 SEG3007H-012, 014, 016, 018, 022, 024, 058, 059, 060 SEG3007V-231, 232, 235~252

WELDING

TA-Yard

This QA Inspector randomly observed the following work in progress:

Shielded Metal Arc Welding (SMAW)

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as SEG3020*-002 located on deck plate of the OBG Segment 14W. The welder is identified as 037748. ZPMC Quality Control (QC) is identified as Mr. Zhu Lin. The welding variables recorded by QC appeared to comply with WPS-B-P-2214-Tc-U4b-FCM-1.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey-15000026784, who represents the Office of Structural Materials for your project.

Inspected By:	Singh,Vikram	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer